	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
1	I		34/\$.ccls. 134/\$.ccls.	USPAT; EPO; JPO	2004/03 /01			0
2	BR S	344	(34/\$.ccls. 134/\$.ccls.) and (substrate wafer) and vacuum and cassette	USPAT; EPO; JPO	2004/03 /01 11:45			0
3	BR S		((34/\$.ccls.) and (substrate wafer) and vacuum and cassette) and (transfer with cassette) and (original with cassette with return)	USPAT; EPO; JPO	2004/03 /01 11:46			0
4	BR S	50	((34/\$.ccls. 134/\$.ccls.) and (substrate wafer) and vacuum and cassette) and (transfer with cassette) and (original with cassette)	USPAT; EPO; JPO	2004/03 /01 11:49			0
5	BR S	43	((34/\$.ccls. 134/\$.ccls.) and (substrate wafer) and vacuum and cassette) and (transfer with cassette) and (original with cassette) and dummy	USPAT; EPO; JPO	2004/03 /02 09:14			0
6	BR S	1	"4923584".PN.	USPAT	2004/03 /01			0
7	BR S	1	4923584.pn. and (plasma dummy)	USPAT; EPO; JPO	2004/03 /01			0

	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
8	BR S		(((34/\$.ccls. 134/\$.ccls.) and (substrate wafer) and vacuum and cassette) and (transfer with cassette) and (original with cassette) and dummy) not kato	USPAT; EPO; JPO	2004/03 /02 09:15			0
9	BR S	43	((34/\$.ccls. 134/\$.ccls.) and (substrate wafer) and vacuum and cassette) and (transfer with cassette) and (original with cassette) and dummy	USPAT; EPO; JPO	2004/03 /02 09:16			0

	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
10	BR S	48	("3652444"   "3981791"   "4138306"   "4226897"   "4311427"   "4313815"   "4318767"   "4449885"   "4457661"   "4534314"   "4576698"   "4576698"   "4634331"   "4643629"   "4715764"   "4824309"   "4836733"   "4836733"   "4895107"   "4902934"   "4902934"   "4903937"   "4903937"   "4903937"   "4903937"   "4903937"   "4903937"   "4903937"   "4903937"   "4903937"   "4903937"   "4903937"   "4903937"   "4903937"   "4903939"   "4915564"   "4917556"   "4923584"   "4924890"   "4936329"   "4951601"	USPAT	2004/03 /02 09:15			0

	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
11	BRS	1	(("3652444"   "3981791"   "4138306"   "4226897"   "4311427"   "4313783"   "4313815"   "4449885"   "4457661"   "4563240"   "4576698"   "4576698"   "4634331"   "4643629"   "4715764"   "4824309"   "4836733"   "4836905"   "4851101"   "4895107"   "4902934"   "4902934"   "4903937"   "4909695"   "4915564"   "4917556"   "4917556"   "4924890"   "4936329"   "4936329"   "4951601"	USPAT; EPO; JPO	2004/03 /02 09:16			0
12	BR S		(34/\$.ccls. 134/\$.ccls.) and ((substrate wafer) with dummy) and @py<1990	USPAT; EPO; JPO	2004/03 /02 09:28			0

	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
13	BR S	13	(34/\$.ccls. 134/\$.ccls.) and ((substrate wafer) with dummy) and @py<1993	USPAT; EPO; JPO	2004/03 /02 09:28			0
14	BR S		((34/\$.ccls. 134/\$.ccls.) and ((substrate wafer) with dummy) and @py<1993) not ((34/\$.ccls. 134/\$.ccls.) and ((substrate wafer) with dummy) and @py<1990)	USPAT; EPO; JPO	2004/03 /02 09:30			0
15	BR S	63	kato and (wafer substrate) and 34/\$.ccls.	USPAT; EPO; JPO	2004/03 /02 09:30			0
16	BR S	14	(kato and (wafer substrate) and 34/\$.ccls.) and kathryn	USPAT; EPO; JPO	2004/03 /02 09:31			0

	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
1 1 / 1	$^{ m BS}$	49	("3652444"   "3981791"   "4138306"   "4226897"   "4311427"   "4313783"   "4313815"   "4449885"   "4457661"   "4534314"   "4563240"   "4576698"   "4634331"   "4643629"   "4705951"   "4715764"   "4824309"   "4836733"   "4836733"   "4836905"   "4851101"   "4895107"   "4902934"   "4902934"   "4903937"   "4903937"   "4903937"   "4915564"   "4917556"   "4917556"   "4917556"   "4924890"   "4936329"   "4951601"	USPAT	2004/03 /02 09:31			0

	Ty pe	Hits	Search Text	DBs	Time Stamp	Com ments	Error Defini tion	Error s
18	BR	3	(("3652444"   "3981791"   "4138306"   "4226897"   "4311427"   "4313815"   "4318767"   "4449885"   "4457661"   "4534314"   "4576698"   "4576698"   "4634331"   "4643629"   "4715764"   "4824309"   "4836733"   "4836905"   "4851101"   "4895107"   "4902934"   "4902934"   "4903937"   "4909695"   "4915564"   "4917556"   "4917556"   "4924890"   "4936329"   "4936329"   "4951601"	USPAT; EPO; JPO	2004/03 /02 09:31			0

	Document ID	Issue Date	I ITIE		Curren t XRef	INVENTAR
1	US 5169407 A	1992 1208	Method of determining end of cleaning of semiconductor manufacturing apparatus	29/25.	134/1; 204/19 2.33; 204/29 8.32; 216/59	Mase, Yasukazu et al.
2	US 5016663 A	1991	Method of determining end of cleaning of semiconductor manufacturing apparatus	134/1	134/1.1 ; 204/19 2.33; 204/29 8.32;	Mase, Yasukazu et al.
3	US 4827867 A	1989 0509	Resist developing apparatus	118/6	118/32 0; 118/32 6; 118/52; 118/66 7; 134/10 5; 134/20 0; 134/90 2; 165/15 6; 165/16 9; 165/28 9; 165/64; 427/42 2	Takei, Toshitaka et al.

	Document ID	Issue Date	l itle	1	Curren t XRef	Inventor
4	US	1086	Method of depositing silicon films with reduced structural defects		134/22. 18; 134/37; 438/68 4:	Wonsowicz, Casimir J. et al.
5	US 4529474 A	1985 0716	Method of cleaning apparatus for forming deposited film	134/1. 1	004/10	Fujiyama, Yasutomo et al.
6	US 4512812 A	0423	Method for reducing phosphorous contamination in a vacuum processing chamber	134/2 1	134/22. 18; 134/30; 134/31; 134/42	Liebert, Reuel B. et al.
7			, ,	34/23 9		Takagi, Mikio et al.

	Document ID	Issue Date	l Title		Curren t XRef	INVENTOR
8			Method for removing photoresist by hydrogen plasma	430/3 23	134/1; 134/1.2; 204/19 2.32; 216/59; 257/E2 1.249; 257/E2 1.256; 315/11 1.21; 430/32 9; 430/49	Frederick J.
9	Љ 03064916 A	1991 0320	WAFER WASHING METHOD	·	134/90	MIYAMOT O, YASUNOR I
10	JР 63185032 A		ETCHING APPARATUS FOR SILICON SUBSTRATE		134/41	NONAKA, TSUTOMU
11	JP 62023116 A	1987 0131	WET SEMICONDUCTOR MANUFACTURING EQUIPMENT	·	34/3X	ЕЛПІ, IWAO
12	JP 59229822 A	1984 1224	ETCHING APPARATUS		134/1; 257/E2 1.215	NITTA, TAKEHISA
13	JP 58009325 A		SELF-ROTATIONAL WAFER DRYER		34/58; 34/108	OKUMUR A, KATSUYA